


BMW 7-Serie Limousine F01 / F02

11/08 >> 02/14



Installation instructions

Reference:




The following information must be reviewed before beginning the assembly:


The installation instructions are to be thoroughly read.


The installation should be carried out by qualified personnel with the relevant technical knowledge. The vehicle manufacturers' current technical notices and information on retrofitting must be followed. The removal and replacement instructions found in the current repair manuals must be followed. It must be ensured that the vehicle is technically suitable for the installation of a trailer hitch.

KIT




TOOLS








ROUTING





REMOVE





























11 **OPTION 1** 21











750018-180315B8 10 / 20

13 OPTION 2




14 OPTION 2




15 **OPTION 2 ⊘ ⇒ 21**




















20	\Rightarrow	21


1	ye	\triangleleft
2	bk	1 3 2 4 (R)
3	wh	÷
4	gn	ightharpoonup
5	bu	
6	rd	Stop
7	bn	


21	bk	wh	gy	gn	rd	bu	ye	bn	pu	or	no
GB	black	white	grey	green	red	blue	yellow	brown	purple	orange	not occupied

750018-180315B8 15 / 20












750018-180315B8 16 / 20


24 CHECK ALL LIGHTING FUNCTIONS




25 CHECK BULB OUT DETECTION









750018-180315B8 17 / 20




PDC

If the PDC does not automatically deactivate, coding and initialization of the module might be required.








OPTION 1





No Coding



OPTION 2







OPTION 3






BMW Service ISTA/P Initialize Trailer Module







750018-180315B8 19 / 20






Please effect coding as follows:

- Connect computer to vehicle
- Start ISTA/P
- Click "Modification / Upgrades"
- Scan Action plan
- Click "Coding (Ethernet)"
- Scan Action program follow-up
- Final report checking

After the effected connection, the rear park assist system will also automatically be deactivated in trailer operation!





Subject to change in terms of construction, equipment and colour, and may contain errors.

The information and illustrations are non-binding.

750018-180315B8 20 / 20

Status LED for self-diagnosis

