		TRA	ILB	<u>C</u> SS	5	
	То	Suit NISSAN P Part	Fitting Instr ATHFINDI Number DS ting 1500Kg	ER 7/05 onwar 80	rds	
WARN 1. 2.	Do not, drill, cut, weld or If you are using electri	ic welding on a mot strument manageme	or vehicle, alv nt equipment.	Failure to do s	ne vehicle is not equipped with o could <u>destroy</u> any onboard	
1. 2. 3.	Ensure all hardware item Remove spare wheel. Cut the bottom most fac			gram (viewed from ⁻	the underside of the vehicle).	
10		85	=	hate	is 85mm wide, (shown by the ched marking). It is centered ween the mounting points visible either side of the cut.	
4. 5. 6. 7.	Lift Tow bar into position, matching holes in cross beam to holes in tow bar and support with a jack or similar. Fit M12 x 80mm bolts through aligned holes in the tow bar and cross beam from the bottom up, while tapped plates on wires are positioned above the cross beam. Tighten these 6 bolts hand tight before lowering jack. Fasten all bolts & nuts to torque listing below. Trim excess wire off tapped plates if necessary.					
	NOTE: It is recom Australian	mended that you o Design Rules.	check your to	ow ball to ensur	re it complies with	
	MMENDED ASSEMBLY TO Ide 8.8 Bolt	DRQUE LISTING				
Diame M6 M8 M10 M12 M16	9.5 21.7 43.4			FOR TOWING PURPOSES ONLY For towing capacity details please refer to vehicle owner's manual or to the manufacturer.		
L I	Page 1 of 2	THE WORKHON	RSE OF AUSTR	ALIA'S TOWBARS	Issue Date 05-10-05	

